# New York State Department of Transportation PIA Safety Flag NB23CTW005

By: Rehan Afridi

Flag Date: June 07, 2023

Superseding Information:

No Flags Superseded

#### Structure Information

BIN: 1065318 Region: 11 - NEW YORK CITY

Feature Carried: 278I278IX2M23027 County: KINGS

Feature Crossed: 6TH AVENUE Political Unit: City of NEW YORK
Orientation: 8 - NORTHWEST Approximate Year Built: 1962

Posted Load Matches Inventory: Yes

Bridge Load Posting (Tons): Not Posted for Load

Primary Owner: New York State Department of Transportation

Primary Maintenance Responsibility: 12 - State - Subcontracted to another Party

Typical or Main Span Type: 3 - Steel, 02 - Stringer/Multi-Beam or Girder

This Bridge is not a Ramp Number of Spans: 322

#### **Verbal Notification Information**

Person Notified: Muhammad Mubeen Date: June 07, 2023 2:15:00 PM

Of: NYSDOT Region 11

#### Signature Information

Signature: Rehan Afridi, P.E. 075185 Date: June 08, 2023

Reviewed By: Robert Kemp Date: June 08, 2023

Attachments: 4

Flag Date: June 07, 2023

### Flagged Elements

# **No Flagged Elements**

### Flagged Condition Description


This PIA Safety Flag No. NB23CTW005 is a New Flag. Location: Span 138, Pier 137, Column C2 at the base.

At Span 138, Pier 137 Column C2, End face, there is a corroded and broken electrical junction box which exhibits exposed live wires. The condition is at the base of the column, and is accessible by the public.

The subject location is at 44th Street and 3rd Avenue eastbound.

Flag Date: June 07, 2023

## Flag Photographs



Flag Date: June 07, 2023

Photo Number: 2 Photo Filename: IMG\_2456.JPG



Attachment Description: General view of Flagged location. Looking Begin.



Attachment Description: Location of Flagged condition at Pier 137, Column C2. Looking Begin.



Attachment Description: Close-up view of the junction box with exposed live wires. Looking Begin.